



Download from
Dreamstime.com
This watermarked comp image is for previewing purposes only.

ID 35103813
© Yulia Gapeenko | Dreamstime.com

[Gtx-1070-problems](#)

GPU	GPU	GPU
NVIDIA GeForce GTX 1070	NVIDIA GeForce GTX 1070	NVIDIA GeForce GTX 1070
GPU: GP104, Revision: A1	GPU: GP104, Revision: A1	GPU: GP104, Revision: A1
Technology: 16 nm, Die Size: 314 mm²	Technology: 16 nm, Die Size: 314 mm²	Technology: 16 nm, Die Size: 314 mm²
Release: May 7, 2016, Transistors: 7200M	Release: May 7, 2016, Transistors: 7200M	Release: May 7, 2016, Transistors: 7200M
BIOS Version: 86.04.1E.00.41	BIOS Version: 86.04.1E.00.70	BIOS Version: 86.04.1E.00.77
Device ID: 10DE-1B81, Subvendor: MSI (1462)	Device ID: 10DE-1B81, Subvendor: EVGA (3842)	Device ID: 10DE-1B81, Subvendor: NVIDIA (10DE)
ROPs/TMUs: 64 / 120, Bus Interface: PCI-E 3.0 x16 @ x16 1.1	ROPs/TMUs: 64 / 120, Bus Interface: PCI-E 3.0 x16 @ x16 1.1	ROPs/TMUs: 64 / 120, Bus Interface: PCI-E 3.0 x16 @ x16 1.1
Shaders: 1920 Unified, DirectX Support: 12 (12_1)	Shaders: 1920 Unified, DirectX Support: 12 (12_1)	Shaders: 1920 Unified, DirectX Support: 12 (12_1)
Pixel Fillrate: 101.2 GPixel/s, Texture Fillrate: 189.8 GTexel/s	Pixel Fillrate: 102.8 GPixel/s, Texture Fillrate: 192.8 GTexel/s	Pixel Fillrate: 103.7 GPixel/s, Texture Fillrate: 194.4 GTexel/s
Memory Type: GDDR5 (Samsung), Bus Width: 256 Bit	Memory Type: GDDR5 (Samsung), Bus Width: 256 Bit	Memory Type: GDDR5 (Samsung), Bus Width: 256 Bit
Memory Size: 8192 MB, Bandwidth: 256.3 GB/s	Memory Size: 8192 MB, Bandwidth: 256.3 GB/s	Memory Size: 8192 MB, Bandwidth: 262.7 GB/s
Driver Version: 10.18.13.6839 WHQL (ForceWare 368.39) / Win10 64	Driver Version: 10.18.13.6881 WHQL (ForceWare 368.81) / Win10 64	Driver Version: 10.18.13.6881 WHQL (ForceWare 368.81) / Win10 64
GPU Clock: 1582 MHz, Memory: 2002 MHz, Boost: 1772 MHz	GPU Clock: 1607 MHz, Memory: 2002 MHz, Boost: 1797 MHz	GPU Clock: 1620 MHz, Memory: 2052 MHz, Boost: 1823 MHz
Default Clock: 1582 MHz, Memory: 2002 MHz, Boost: 1772 MHz	Default Clock: 1607 MHz, Memory: 2002 MHz, Boost: 1797 MHz	Default Clock: 1620 MHz, Memory: 2052 MHz, Boost: 1823 MHz
NVIDIA SLI: Disabled	NVIDIA SLI: Disabled	NVIDIA SLI: Disabled
Computing: <input checked="" type="checkbox"/> OpenCL, <input checked="" type="checkbox"/> CUDA, <input checked="" type="checkbox"/> PhysX, <input checked="" type="checkbox"/> DirectCompute 5.0	Computing: <input checked="" type="checkbox"/> OpenCL, <input checked="" type="checkbox"/> CUDA, <input checked="" type="checkbox"/> PhysX, <input checked="" type="checkbox"/> DirectCompute 5.0	Computing: <input checked="" type="checkbox"/> OpenCL, <input checked="" type="checkbox"/> CUDA, <input checked="" type="checkbox"/> PhysX, <input checked="" type="checkbox"/> DirectCompute 5.0

[Gtx-1070-problems](#)



Download from
Dreamstime.com
This watermarked comp image is for previewing purposes only.

ID 35103813
© Yulia Gapeenko | Dreamstime.com

